

Report ID: 17,895,785 Version: 1 Created: 21 May 2018

Make:	Subaru	Model:	Outback	Body Style:	SUV		Pass	Fail	N/A
Year:	2,014	Registration:	HLG65	Reg Expiry:	25 Sep 2018	Engine	1		I
WoF Expiry:	,	Odometer:	152,751 Kms	Good No:	17895785	Oil level	~		
VIN:	JF2BRMKC5EG064276	Next Service:	163861	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Dauta have used	harmaltan and an	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	S	-0		-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rurt SSC DD D						Operation	Operation		
R = rust PT = paint defe				$\prod$		Noise	~		
C = crack				$+ \mathbf{\nabla}$	R SC	Clutch	•		~
P = pin dent					<i>л</i> ш	CV joints	~		•
* = decals	sc 916			The		Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs D W D D D						Performance	~		
Deskulas		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
								mm	
						Right front		, 1	mm
						Left rear		5	mm
Conditions During Body Inspection: Drv						Right rear	5 mm		
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	. Good					Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
	I				1	Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
Inspected by: John Lindsay Date: 21 May 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....