

Report ID: 17,896,633 Version: 1 22 May 2018 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,012	<b>Registration:</b>	GLR654	Reg Expiry:	29 Jul 2018	Engine	1		L
WoF Expiry:		Odometer:	153,756 Kms	Good No:	17896633	Oil level	~		
VIN:	6G1EP5E22CL625295	Next Service:	156300	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
	SC		SC		SC	Performance	~		
Key:	LSC (L	-0		500-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	smission		
R = rust SC A A A A A A A A A A A A A A A A A A						Operation	~		
PT = paint def	ect NP				17111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HP				74116	CV joints			~
* = decals SC 99						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC W		SC			Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Stone chips front screen.						Tyres (lowest observed tread depth of tyres)			
					Left front	6 mm			
						Right front	e	5	mm
						Left rear	3	3	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine cov	er missing.					Suspension performance	~		
						Steering performance	<		
Shock absorber							~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	<		
Panels	Good					Dashboard warning lights	~		
Dashhaa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	<b>-</b> .				]	Window winder FR	۲		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	2		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism:						Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)	~		
	or Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Brian Hill Date: 22 May 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....