

## **Basic Vehicle Condition Guide**

Report ID: 17,900,228


Version:

Created: 17 May 2018

Make: Model: Mazda Atenza **Body Style:** Sedan Year: 2,013 Registration: Reg Expiry: **WoF Expiry: Odometer: Good No:** 14 May 2019 127,511 Kms 17900228 VIN: 7AT0C139X18203507 **Next Service:** 137000 **Service History:** 

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

**General Comments** 

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Bobby Zhong Date: 17 May 2018

Name: .....

	Pass	Fail	N/A		
Engine					
Oil level	~				
Smoke & fumes	\( \times \)				
Performance	~				
Noise	~				
Cooling System					
Coolant condition	~				
Performance	~				
Radiator / Hoses (visual)	~				
Transmission					
Operation	~				
Noise	~				
Clutch			~		
CV joints	~				
Wheel bearings	~				
Brakes					
Performance	~				
Hand Brake	~				
Tyres (lowest observed tread depth of tyres)					
Left front	7.0		mm		
Right front	7.0		mm		
Left rear	7.0		mm		
Right rear	7.0		mm		
Spare		Yes			
Suspension					
Suspension performance	~				
Steering performance	\( \sigma \)				
Shock absorbers	~				
Air Conditioning / Heater					
Operation	~				
Electrical / Accessories					
Head lights	~				
Tail lights	~				
Indicators	~				
Dashboard warning lights	\( \times \)				
Wipers (front & rear)	~				
Window winder FL	\( \times \) \( \t				
Window winder FR	~				
Window winder RL	~				
Window winder RR	~				
Rear view mirrors					
Radio (basic test only)	<b>'</b>				
CD (basic test only)	~				
Number of keys	2		1		
Central locking	<b>'</b>				
Remote locking	<b>'</b>		<u> </u>		
Sat. Nav. (basic test only)			<b>'</b>		
Reversing camera					

Signature: .....