

Report ID: 17,900,696 Version: 1 29 Aug 2018 Created:

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,017	Registration:	KHU359	Reg Expiry:	01 Jun 2018	Engine			
WoF Expiry:	,-	Odometer:	37,307 Kms	Good No:	17900696	Oil level	~		
VIN:	6G1PD6EM7GL250633	Next Service:	45000	Service Histor	<b>y:</b> Yes	Smoke & fumes	V		
						Performance	V		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	r		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	harge.	Coolant condition	V		
						Performance	~		
Key:	SC	-0	S SC S SC	-01-	s	Radiator / Hoses (visual)	V		
S = scratch						Transmission			
D = dent R = rust	scw bla			715	HILS	Operation	~		
PT = paint def				$\left( \left  \right\rangle \right)$		Noise	V		
C = crack					S	Clutch			~
P = pin dent	HID				74116	CV joints	~		
* = decals	s gig				ALD'S	Wheel bearings	V		
SC = stone chips						Brakes			
W = significan	S SC		P SC		S SC	Performance	V		
Podulaci	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			
					Left front 6.3			mm	
						Right front		.3	mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry						Right rear		.2	mm
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
No underbo	ody inspection					Suspension performance	~		
						Steering performance	V		
						Shock absorbers	V		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	V		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General (	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Conditions During Test Drive: Dry						Central locking	~		
			-			Remote locking	~		
	ming Mechanism:	Cambelt	t			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jamie Cook Date: 29 Aug 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....