

Basic Vehicle Condition Guide

Report ID: 52,610


Version: 1

Created: 23 May 2018

Make: Model: Holden Captiva 5 **Body Style:** SUV Year: 2,013 Registration: **GWP815** Reg Expiry: 11 Feb 2019 WoF Expiry: **Odometer: Good No:** 31 May 2019 17902460 53,125 Kms VIN: KL3DA26UJDB040594 **Next Service: Service History:** Just Serviced Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Under Carriage & Under Bonnet Inspection Comments

Conditions During Body Inspection:

<u>Interior Comments</u>			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

Dry

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: DM Autos Date: 17 May 2018

	Pass	Fail	N/A
Engine	•	•	
Oil level	~		
Smoke & fumes	v		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	<i>V</i>		
Radiator / Hoses (visual)	~		
Transmission	•		•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	8	.0	mm
Right front	8	.0	mm
Left rear	6.0		mm
Right rear	6	6.0	
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories	•		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	V V V V V V V V		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	V		
Remote locking	~		
	<i>'</i>		~

I have read and understood this condition guide.

Name:

Signature: