

Report ID: 17,903,605 Version: 1 18 May 2018 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2,015	Registration:	JGB868	Reg Expiry:	30 Jul 2018	Engine			
WoF Expiry:	31 Jul 2018	Odometer:	47,474 Kms	Good No:	17903605	Oil level	~		
VIN:	MMU148EK0GH60750	Next Service:		Service Histor	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
					D	Performance	~		
Key:		-0	SD S			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
D = dent R = rust	s sc			715	HIVS	Operation	~		
PT = paint defe	ect NP	r I				Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIP				74 <u>11</u> 4	CV joints	~		
* = decals	sc 916			To .		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv = significan			D D			Performance	~		
Body Inst	paction Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			
					Left front	5 mm			
						Right front	5		mm
						Left rear	6		mm
Conditions During Body Inspection: Wet						Right rear	5	5	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leak						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	stains					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	1		•
Road Conditions During Test Drive: Wet						Central locking	~		
	-					Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 18 May 2018									

I have read and understood this condition guide.

Name:

Signature: