

Report ID: 17,904,562 Version: 1 18 May 2018 Created:

Make:	Nissan	Model:	Tiida	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:		Reg Expiry:		Engine	1	I	1
WoF Expiry:	10 May 2019	Odometer:	49,955 Kms	Good No:	17904562	Oil level	~		
VIN:	7AT0DH78X18310187	Next Service:	59,952kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for any and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HE			TIN		Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack						Clutch			~
P = pin dent					세비	CV joints	~		
* = decals	616			The	ELIPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inst	pection Comments	1010.501		indy not be disp	ayea in the alagram	Tyres (lowest observed treat	•	oftyre	
						Left front 3 mm			
						Right front		-	mm
						Left rear		3	mm
								3	
Conditions During Body Inspection: Dry						Right rear 4 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Tidy.	inage a onder bor	meemspeede	<u>Comments</u>			Suspension			
nuy.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General Comments Tidy, low km Tiida.						Window winder RL	~		
i iay, low kr	n maa.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
	-					Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Daryll Timms Date: 18 May 2018									

I have read and understood this condition guide.

Name:

Signature: