

Report ID: 17,904,673 Version: 2 08 Jun 2018 Created:

Make:	Mazda	Model:	Axela	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,004	Registration:	ELG551	Reg Expiry:	06 Jul 2018	Engine			
WoF Expiry:	12 Apr 2019	Odometer:	121,720 Kms	Good No:	17904673	Oil level	~		
VIN:	7A8C13J0708104651	Next Service:	131000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	D	-0	S	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust PT = paint defe				\int	JHH	Noise	~		
C = crack						Clutch	•		~
P = pin dent					ᅰЦ	CV joints	~		•
* = decals	6/16			The	ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S S S S S						Performance	~		
		Note: som	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments	Note: Joh		indy not be disp	ayea in the diagram	Tyres (lowest observed tread	-	oftyre))
						Right front		5	
						Left rear		5	mm
								3	mm
Conditions During Body Inspection: Dry						Right rear 3		mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
						· ·			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Good					Tail lights	~		
· · ·	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
Conoral						Window winder FR	~		
General Comments A/c switch unit need attention						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test		Central locking	~					
Engine Th	ning Machanian		- ·]	Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Bobby Zhong Date: 08 Jun 2018									
Inspected by. Bobby 21001g Date: 08 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: