

Report ID: 17,904,723 Version: 1 20 May 2018 Created:

Make:	Eunos	Model:	Roadster	Body Style:	Convertible		Pass	Fail	N/A
Year:	1,990	Registration:	XW5460	Reg Expiry:	01 Oct 2018	Engine			
WoF Expiry:	09 Sep 2018	Odometer:	202,603 Kms	Good No:	17904723	Oil level	~		
VIN:	7A8N6000799118266	Next Service:	Unknown.	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or	Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	P	-0	<u>s</u>	-M-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust D S S						Operation		~	
PT = paint defe				$\left[\left(\right) \right]$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints			~
* = decals						Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs S W S P						Performance	~		
Pedular	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
AC knob missing									mm
						Right front		5	mm
						Left rear		, 1	mm
Conditions During Body Inspection: Dry					Right rear	5 mm		mm	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension				
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Avelage					Indicators	~		
Panels	Console pa	anel cracked				Dashboard warning lights	~		
<u> </u>	Cracked					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1					Window winder FR	~		
General Comments					Window winder RL			~	
Engine tapping noise Transmission shift delay						Window winder RR			~
	on shint delay					Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)			~
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking			~
						Remote locking			~
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
Inspected by: Mathew Varghese Date: 20 May 2018									

I have read and understood this condition guide.

Name:

Signature: