

Report ID: 17,907,359 Version: 1 Created: 22 May 2018

Make:	Audi	Model:	A3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,009	Registration:		Reg Expiry:		Engine	1	<u> </u>	1
WoF Expiry:		Odometer:	79,580 Kms	Good No:	17907359	Oil level	~		1
VIN:	WAUZZZ8P99A08635	Next Service:	89600	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	aration is made	for ago and milaago	Parts have not	boon dismonthed or	Noise	~		
diagnostic te	sting undertaken. The	vehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System			
a full mechar	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional o	charge.	Coolant condition	~		1
						Performance	~		
Key:		-0	S PT P	-161-		Radiator / Hoses (visual)	~		<u> </u>
S = scratch	TE	A U			Ton	Transmission			1
D = dent R = rust	- HE			715	HIL	Operation	~		
PT = paint def		F		$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	- Alf			-No-		Wheel bearings	~		
SC = stone chi	/	20		10-	*	Brakes			1
W = significan			P			Performance	~		
Podulaci	action Commonts	Note: som	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
<u>bouy ins</u>	pection Comments					Tyres (lowest observed tread	d depth	of tyre	1 2s)
						Left front		-	mm
						Right front	e		mm
						Left rear	e		mm
Conditions During Body Inspection: Dry						Right rear	e	-	mm
Conditions During Body Inspection: Dry						Spare Yes			
<u>Under Ca</u>	irriage & Under Bor	net Inspectio	on Comments			Suspension		105	
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			1
						Operation	~		
Interior Comments						Electrical / Accessories			<u> </u>
Seats	Good					Head lights	~		
	Good					Tail lights	~		<u> </u>
Carpets						Indicators	~		1
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		1
Dashboa	ird					Window winder FL	~		
	I					Window winder FR	~		<u> </u>
General Comments					Window winder RL	~			
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
						•			
Inspecte	d by: John Lindsay					Date: 22 May 20	18		

I have read and understood this condition guide.

Name:

Signature: