Make:	Toyota	**Model:**	Hiace	**Body Style:**	Van	
Year:	2,014	**Registration:**		**Reg Expiry:**		
WoF Expiry:	17 May 2019	**Odometer:**	59,776 Kms	**Good No:**	17908921	
VIN:	7AT0H60FX18021151	**Next Service:**	69000	**Service History:**	No	

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments
Clean

Interior Comments

Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No   Kms:

	Pass	Fail	N/A
Engine			
Oil level	✔		
Smoke & fumes	✔		
Performance	✔		
Noise	✔		
Cooling System			
Coolant condition	✔		
Performance	✔		
Radiator / Hoses (visual)	✔		
Transmission			
Operation	✔		
Noise	✔		
Clutch			✔
CV joints			✔
Wheel bearings	✔		
Brakes			
Performance	✔		
Hand Brake	✔		
Tyres (lowest observed tread depth of tyres)			
Left front	4	mm	
Right front	4	mm	
Left rear	3	mm	
Right rear	3	mm	
Spare	Yes		
Suspension			
Suspension performance	✔		
Steering performance	✔		
Shock absorbers	✔		
Air Conditioning / Heater			
Operation	✔		
Electrical / Accessories			
Head lights	✔		
Tail lights	✔		
Indicators	✔		
Dashboard warning lights	✔		
Wipers (front & rear)	✔		
Window winder FL	✔		
Window winder FR	✔		
Window winder RL			✔
Window winder RR			✔
Rear view mirrors	✔		
Radio (basic test only)	✔		
CD (basic test only)			✔
Number of keys	3		
Central locking	✔		
Remote locking	✔		
Sat. Nav. (basic test only)			✔
Reversing camera			✔

Inspected by: Stuart Melbourne

Date: 01 Aug 2018

I have read and understood this condition guide.   Name: ……………………………………   Signature: ……………………………