

Report ID: 17,910,429 Version: 1 Created: 23 May 2018

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,006	<b>Registration:</b>	DBW296	<b>Reg Expiry:</b>	01 Jul 2018	Engine			
WoF Expiry:	16 Apr 2019	Odometer:	229,773 Kms	Good No:	17910429	Oil level	~		
VIN:	JM0BK10F100177490	Next Service:	234000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged to	or an additional c	narge.	Coolant condition	~		
	s w		S	W	S	Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust SC W A A A A A A A A A A A A A A A A A A						Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HP				24114	CV joints	~		
* = decals	sc 916	10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significant scuris sc w sc sc						Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Stone chips front screen.						Tyres (lowest observed tread depth of tyres)			
Stone emps none serveri.						Left front	ront <sub>6</sub> mr		
						Right front	6	5	mm
						Left rear	2	ł	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Silv						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good				1	Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Central locking	~						
			Dry			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 23 May 2018									

I have read and understood this condition guide.

Name: .....

Signature: .....