

Report ID: 17,911,223 Version: 2 Created: 19 Jul 2018

Make:	Ford	Model:	Ecosport	Body Style:	SUV		Pass	Fail	N/A
Year:	2,016	Registration:	KDD159	Reg Expiry:	01 Jun 2018	Engine			
WoF Expiry:	2,010	Odometer:	65,054 Kms	Good No:	17911223	Oil level	~		
VIN:	MAJBXXMRKBGK1946	Next Service:	Unknown	Service Histor		Smoke & fumes	~		
					,	Performance	~		-
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		1
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	6/6			The	EIU/	Operation	~		
R = rust PT = paint def				\prod	JHIA	Noise	~		
C = crack				+		Clutch	-		~
P = pin dent						CV joints	~		
* = decals	- MIK			AL.	EITR w	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance			
		Note: con			layed in the diagram				
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	d dopth	of +	
Stone chips to f /screen						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage & onder bor	met inspectio	<u>on comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
	Good					Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	_					Window winder FR	~		
<u>General (</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		•
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
	-		- ,			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
						L			
Inspected by: Murray Craig Date: 19 Jul 2018									
I have read	and understood th	is condition c	uide. Name: .			Signature:			