

Report ID: 17,911,321 Version: 1 Created: 09 Oct 2018

Make:	Holden	Model:	Cruze	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2017	<b>Registration:</b>	KJA850	<b>Reg Expiry:</b>	01 Jun 2018	Engine			
WoF Expiry:		Odometer:	39,155 Kms	Good No:	17911321	Oil level	~		
VIN:	6G1PD6EMXGL24919	Next Service:	unknown	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and ti	his can be arranged to	r an additional c	narge.	Coolant condition	~		
	SC W		SC W S SC W			Performance	~		
Key:		=	30 330	5(0)-		Radiator / Hoses (visual)	V		
S = scratch D = dent						Transmission			
R = rust PT PR						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	sc dle				74IIL	CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scons SC W SC S SC W						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Fine chips of						Tyres (lowest observed tread	d depth	of tyre	÷s)
						Left front 3 r			mm
						Right front	4	1	mm
						Left rear		2	mm
Conditio	ns During Body Ins	pection:	Dry			Right rear	3	3	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy .						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
	Operation	~							
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
Dastibua						Window winder FL	~		
						Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
Nice hatch						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		<b> </b>
Engine Timing Mechanism: Cambelt						Remote locking	~		
						Sat. Nav. (basic test only)			~
	ог сапт вен керіас	ement: N	10	Kms:		Reversing camera			~
Inspected by: Daryll Timms Date: 09 Oct 2018									
I have read and understood this condition guide. Name:									