

Report ID: 17,911,724 Version: 1 12 Jun 2018 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2,008	Registration:	END445	Reg Expiry:	16 Mar 2019	Engine			L	
WoF Expiry:		Odometer:	238,366 Kms	Good No:	17911724	Oil level	~			
VIN:	JM0GH105100110646	Next Service:	248300	Service Histor	-	Smoke & fumes	~			
			2.0000			Performance	~			
	port is not a warranty		с I I		1 B 41 1	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition				
						Performance	~			
Key:	SC	-0	P SC P SC			Radiator / Hoses (visual)	~			
S = scratch	Se	A CO			X	Transmission	•			
D = dent	s sc			The	BID SDC	Operation			<u> </u>	
R = rust				10	JHIK	Noise	レ レ			
PT = paint def C = crack	ect			+	SC	Clutch	V			
P = pin dent	Ho	KI			اللا	CV joints			~	
* = decals	SDSC PR			J.		Wheel bearings	~			
SC = stone chi	ps US	VA		10	& <u> </u>		~			
W = significant scuffs SC S						Brakes			<u> </u>	
		N				Performance	~			
Body Insp	pection Comments	Note: son	ne defects & blemishes	s may not be disp	biayed in the diagram	Hand Brake	~		Ļ	
Minor spider rust on the roof ,						Tyres (lowest observed tread depth of tyres)				
						Left front	7	'	mm	
						Right front	7	,	mm	
						Left rear 4		ŀ	mm	
Conditions During Body Inspection: Wet						Right rear	2 mm			
						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments drivers seat feels loose maybe bolts missing ,						Electrical / Accessories				
Seats	drivers sea	it feels loose may	/be bolts missing ,			Head lights	~			
Compete	Average					Tail lights	~			
Carpets						Indicators	~			
Panels	Average					Dashboard warning lights	~			
	Average					Wipers (front & rear)	~			
Dashboa	ird					Window winder FL	~			
						Window winder FR	~			
General C	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Wet						Central locking	~			
						Remote locking	~		1	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
l										
Inspected by: Donovan Matara Date: 12 Jun 2018										

I have read and understood this condition guide.

Name:

Signature: