

Basic Vehicle Condition Guide

Report ID: 17,914,534


Version: 1

Created: 24 May 2018

Make: Model: Highlander **Body Style:** SUV Toyota Year: 2,014 Registration: Reg Expiry: HPL355 20 Aug 2018 WoF Expiry: **Odometer: Good No:** 21 Aug 2018 17914534 75,317 Kms VIN: 5TDBK3FHX0S061421 **Next Service:** 80000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay

Engine Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch CV joints	Pass V V V V	Fail	N/A
Oil level Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	<i>V V</i>		
Smoke & fumes Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	<i>V V</i>		
Performance Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	V		
Noise Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	V		
Cooling System Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	V V V		
Coolant condition Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	<i>V V</i>		
Performance Radiator / Hoses (visual) Transmission Operation Noise Clutch	V V		
Radiator / Hoses (visual) Transmission Operation Noise Clutch	<i>y</i>		
Transmission Operation Noise Clutch	V		
Operation Noise Clutch			
Noise Clutch	,	•	
Clutch	~		
	/		
CV joints			~
	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front	8	3	mm
Right front	8		mm
Left rear	6		mm
Right rear	6		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	/		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	'		
Rear view mirrors	V		
Radio (basic test only)	V		
CD (basic test only)	'		
Number of keys	3	I	
Central locking	·		
Remote locking	~		
			~
Sat. Nav. (basic test only)	/		<u> </u>
Sat. Nav. (basic test only) Reversing camera			1

I have read and understood this condition guide.

Name:

Signature:

24 May 2018