

Report ID: 17,915,498 Version: 1 Created: 11 Jun 2018

Make:	Subaru	Model:	Impreza	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,007	Registration:	JUG331	Reg Expiry:	10 Nov 2018	Engine	1	I	1
WoF Expiry:	30 May 2019	Odometer:	102,457 Kms	Good No:	17915498	Oil level	~		
VIN:	7AT0GF09X16012794	Next Service:	112400	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and th	his can be arranged f	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	S P SC S P SC	-01-	SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust	s sc			715	HILS	Operation	~		
PT = paint def	ect NP			$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIS				74116	CV joints	~		
* = decals	ssc 916			-Jos		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
w = significan	SC SC		SC SC	796		Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	~		
Body inspection Comments						Tyres (lowest observed trea	l d depth	of tyre	es)
Minor spider rust on the roof ,									mm
						Right front		3	mm
						Left rear		3	mm
Conditio	os During Body Ins	nection:	Drak			Right rear		3	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
	1					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	I	I
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							1	I	1
Inspected by: Donovan Matara Date: 11 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: