

Report ID: 17,916,646 Version: 1 Created: 24 May 2018

| Make: | Ford | Model: | Ranger | Body Style: | Utility | | Pass | Fail | N/A |
|--|---|----------------------|------------------------|-------------------|----------------------|------------------------------|---------|---------|-----|
| Year: | 2,013 | Registration: | GYM774 | Reg Expiry: | 10 Jul 2018 | Engine | | | |
| WoF Expiry: | 31 Aug 2018 | Odometer: | 133,072 Kms | Good No: | 17916646 | Oil level | ~ | | |
| VIN: | MNAUMFF50DW1758 | Next Service: | 132500 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a guide only. Conside | eration is made | for age and mileage. | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tr | his can be arranged to | r an additional c | narge. | Coolant condition | ~ | | |
| | | | S | | S | Performance | ~ | | |
| Key: | | = | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | sc | | | 210 | HIVC | Operation | ~ | | |
| PT = paint def | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | | S | Clutch | ~ | | |
| P = pin dent | IDEC HIP | | | | 24114 | CV joints | | | ~ |
| * = decals SDSC 999 SP | | | | | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| vv – signincan | | | | | | Performance | ~ | | |
| Body Insr | pection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread | d depth | of tyre | es) |
| | | | | | | Left front 5 | | | mm |
| | | | | | | Right front | 5 | 5 | mm |
| | | | | | | Left rear | 8 | | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 8 mm | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Dirty | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | Shock absorbers | ~ | | | | | | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Good | | | | | Head lights | ~ | | |
| | Good | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Good | | | | | Dashboard warning lights | ~ | | |
| | , Good | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | · | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | UT y | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | | | ~ |
| | | | | | | L | | | 1 |
| Inspected by: Stuart Melbourne Date: 24 May 2018 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: