

## **Basic Vehicle Condition Guide**

Report ID: 17,916,679


Version: 2

Created: 03 Jul 2018

Make: Model: Mazda **Body Style:** SUV Premacy Year: 2,006 Registration: Reg Expiry: EHS568 06 Jul 2018 **WoF Expiry: Odometer:** 13 Jun 2019 **Good No:** 17916679 124,563 Kms VIN: 7A8C1330707133749 **Next Service: Service History:** 133000 No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Oil leak

<u>Interior Comments</u>		
Seats	stains	
Carpets	Average	
Panels	Average	
Dashboard	Good	

## **General Comments**

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay Date: 28 May 2018

Name: .....

Pass	Fail	N/A
~		
~		
~		
~		
~		
~		
~		
~		
~		
		~
~		
~		
•		•
~		
~		
d depth	of tyre	es)
4	.0	mm
5.0		mm
6	.0	mm
3.0		mm
Yes		
~		
V		
_		
<i>V</i>		
~		
<i>'</i>		
<i>v</i>	V	
<i>v</i>	v	
V V V V V	~	
V V V V V	v	
V V V V V	~	
V V V V V	~	
V V V V V	~	
V V V V V V V V V V V V V V V V V V V	~	
V V V V V V V V V V V V V V V V V V V	V	
V V V V V V V V V V V V V V V V V V V	~	
V V V V V V V V 1	~	
V V V V V V V V 1		v
	/ / / / / / / / / / / / / / / / / / /	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ

Signature: .....