

I have read and understood this condition guide.

Report ID: 52,003 Version: 2 Created: 12 Jun 2018

Signature:

Make:	BMW	Model:	3 Series	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,008	Registration:	HSG911	Reg Expiry:	01 Jun 2018	Engine			•
WoF Expiry:	21 Jun 2019	Odometer:	169,039 Kms	Good No:	17917194	Oil level	~		
VIN:	WBAVA76000NL2998(Next Service:	Just Serviced	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust						Operation	~		
PT = paint defe				$\left(\right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	-110				세비	CV joints	~		
* = decals	616			-Jul-	AIR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
D. L.L.		Note: son	ne defects & blemishes	may not be disp	blayed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread	-	of tyre	es)
									mm
						Right front		.0	mm
						Left rear		.0 3	mm
Conditions During Pody Inspection, W						Right rear		3	mm
Conditions During Body Inspection: Wet						Spare N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Faileis						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General C	Comments					Window winder RL	~		
Timing chain rattle when cold						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			
Road Conditions During Test Drive: Dry						Central locking	1 V		
Koad Con	aitions During Test	Drive:	Dry			Remote locking	<i>v</i> <i>v</i>		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)			
Evidence of Cam Belt Replacement: Not Applicable Kms:									v
		N				Reversing camera			~
Inspected by: Scott Date: 06 Jun 2018									

Name: