

Report ID: 17,917,269 Version: 1 Created: 01 Jun 2018

Make:	Volkswagen	Model:	Amarok	Body Style:	Utility		Pass	Fail	N/A
Year:	2,014	Registration:	HQL604	Reg Expiry:	02 Sep 2018	Engine			L
WoF Expiry:	2,014 07 Sep 2018	Odometer:	99,638 Kms	Good No:	17917269	Oil level	~		
VIN:	WV1ZZZ2HZEA04643		102,800kms	Service Histor		Smoke & fumes	~		
	WW1ZZZZHZEA04043.		102,800km		• 165	Performance	~		
Note: This report is not a warranty						Noise			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:	SC S		SC P W		SC W	Performance	~		<u> </u>
S = scratch						Radiator / Hoses (visual)	~		
D = dent						Transmission			<del></del>
R = rust	s sc 96				HIV	Operation	~		
PT = paint defect						Noise	~		
						Clutch			~
P = pin dent	PSC DE				~HHS	CV joints	~		
* = decals P 3C SC = stone chips SP						Wheel bearings	~		
W = significant scuffs						Brakes			
W = significant scurs SSC S P W SDC						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Number plate lights not working.						Tyres (lowest observed tread depth of tyres)			
						Left front 2 m			mm
						Right front		)	mm
						Left rear			mm
Conditions During Body Inspection: Dry						Right rear		, 	mm
Conditions During Body Inspection: Dry						Spare	<u> </u>		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
OK.	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
							V		
						Air Conditioning / Heater			1
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Good					Indicators	~		
Panels	Guu					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
Dashbod						Window winder FL	~		
						Window winder FR	~		
General Comments Nice 4x4 d/cab ute.						Window winder RL	~		
INICE 4X4 d/	כמט ענפ.					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		<u> </u>
						-	1		
Inspected by: Daryll Timms Date: 01 Jun 2018									
I have read and understood this condition guide. Name:									