


<b>Make:</b>	Mitsubishi	<b>Model:</b>	L300	<b>Body Style:</b>	Van
<b>Year:</b>	2,006	<b>Registration:</b>	DPL186	<b>Reg Expiry:</b>	29 Jul 2018
<b>WoF Expiry:</b>	16 May 2019	<b>Odometer:</b>	235,252 Kms	<b>Good No:</b>	17917540
<b>VIN:</b>	JMAHNP15V7A80034	<b>Next Service:</b>	235,000kms	<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

R/H head light chipped.  
Stone chips & rust on l/h A pillar.  
Rust on top of l/h door shut.

Note: some defects & blemishes may not be displayed in the diagram

Conditions During Body Inspection: Wet

## Under Carriage & Under Bonnet Inspection Comments

OK.

## Interior Comments

Seats	hole in drivers seat, dirty.
Carpets	hole on drivers side.
Panels	Average
Dashboard	heater knobs missing, mode switch stiff.

## General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 133,000

	Pass	Fail	N/A
Engine			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
Cooling System			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
Transmission			
Operation	✓		
Noise	✓		
Clutch	✓		
CV joints			✓
Wheel bearings	✓		
Brakes			
Performance	✓		
Hand Brake	✓		
Tyres (lowest observed tread depth of tyres)			
Left front	7	mm	
Right front	5	mm	
Left rear	7	mm	
Right rear	8	mm	
Spare	Yes		
Suspension			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
Air Conditioning / Heater			
Operation			✓
Electrical / Accessories			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL			✓
Window winder RR			✓
Rear view mirrors			✓
Radio (basic test only)			✓
CD (basic test only)			✓
Number of keys	1		
Central locking	✓		
Remote locking			✓
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Daryll Timms

Date: 25 May 2018

I have read and understood this condition guide.

Name: .....

Signature: .....