

Report ID: 17,920,217 Version: 2 20 Mar 2019 Created:

Make:	Holden	Model:	Rodeo 4X4	Body Style:	Utility		Pass	Fail	N/A
Year:	2007	<b>Registration:</b>	DRY217	<b>Reg Expiry:</b>	24 Apr 2019	Engine			
WoF Expiry:	20 Mar 2020	Odometer:	196,795 Kms	Good No:	17920217	Oil level	~		
VIN:	MPATFS77H6H57102(	Next Service:	197000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
N						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	e. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
		purchase and ti	lis can be allanged to		inarge.	Coolant condition	~		
	S	$\sim$			S D	Performance	~		
<b>Key:</b> S = scratch		=(0)		5(0)-		Radiator / Hoses (visual)	~		
						Transmission			
R = rust	s sc			10		Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack				$\square$		Clutch			~
P = pin dent	ssc dl				~HHL	CV joints			~
* = decals SC = stone chi		10		70	ED SD	Wheel bearings	~		
W = significant scuffs						Brakes			
			S P			Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front 7			
						Right front	ļ	5	mm
						Left rear	(	5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Underbody	surface rust					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpote	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashhaa	Good					Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Roger King Date: 20 Mar 2019									
Inspected by: Roger King Date: 20 Mar 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....