

Report ID: 17,920,414 Version: 1 13 Jun 2018 Created:

Make:	Holden	Model:	Commodore	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,008	Registration:	ESA302	Reg Expiry:	20 Nov 2018	Engine			
WoF Expiry:	29 May 2019	Odometer:	200,406 Kms	Good No:	17920414	Oil level	~		
VIN:	6G1EX55H89L153861	Next Service:	210300	Service Histor		Smoke & fumes	~		
			2.0000			Performance	~		
	port is not a warranty		c 1 1	D		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:	S D SC	-0	S P SC S P SC	-161-	S P SC	Radiator / Hoses (visual)	~		-
S = scratch						Transmission			<u> </u>
						Operation	~		<u> </u>
R = rust PT = paint def				\prod	JHIH	Noise	~		
C = crack				+		Clutch	•		~
P = pin dent						CV joints	~		-
* = decals	SPSC 916			- AL	ELIPE S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs S P SC	$- \emptyset$	S P SC S P SC		s	Performance	~		
		Note: son	ne defects & blemishes	s may not be disc	laved in the diagram	Hand Brake	~		
	pection Comments	_				Tyres (lowest observed tread	-	of tyre	<u>ا</u>
Minor stone chips in the windscreen ,						Left front 7 mm			
						Right front	7		mm
						Left rear			mm
Conditions During Rody Inspection:						Right rear		1	
Conditions During Body Inspection: Wet						Spare	7 mm		
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		-
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	drivers sea	at side trim broke	en ,			Head lights	~		T
Jeats						Tail lights	~		-
Carpets	Average						~		
Danala	Average					Dashboard warning lights	~		
Panels						Wipers (front & rear)	V V		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		+
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		<u> </u>
Dead Car	ditions During - Tor					Central locking	2		
Road Conditions During Test Drive: Wet						Remote locking	V V		
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			<i>v</i> <i>v</i>
		ľ							*
Inspected by: Donovan Matara Date: 13 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: