

Report ID: 17,921,990 Version: 2 Created: 27 Jun 2018

Make:	Holden	Model:	Viva	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,007	<b>Registration:</b>	EDM157	Reg Expiry:	26 Sep 2018	Engine	1	I	L
WoF Expiry:	08 Sep 2018	Odometer:	116,916 Kms	Good No:	17921990	Oil level	~		
VIN:	KL3NF35BJ7K510846	Next Service:	117,000kms	Service Histor	<b>y:</b> Yes	Smoke & fumes	V		
						Performance	V		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	V		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	~		
Key:	sc	-0	W S		w	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC D R S						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC SC SC SW SW SW						Performance	~		
Note: come defecte 8 blamiches may not be dienlayed in the diagram						Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	-	oftyre	
Stone chipped screen.						Left front			mm
						Right front		.0	mm
						Left rear		.0	mm
							-	.0	
Conditions During Body Inspection: Wet						Right rear	4.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
<u>онаст са</u> ОК.	indge a onder bor	meenspeede	<u>eennents</u>			· ·			1
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
	Average					Electrical / Accessories			
Seats	5					Head lights	~		-
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels	/weitige					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<b> </b>
Ganaral	-ommonts					Window winder FR	~		<u> </u>
	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Wet			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 11	4,000	Reversing camera			~
Inspected by: Darvil Timms Date: 20 May									
Inspected by: Daryll Timms Date: 29 May 2018									
I have read and understood this condition guide. Name:									