

Report ID: 17,922,194 Version: 2 Created: 09 Jul 2018

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,008	Registration:	JWY316	Reg Expiry:	23 Dec 2018	Engine			1
WoF Expiry:	08 Jun 2019	Odometer:	51,802 Kms	Good No:	17922194	Oil level	~		
VIN:	7AT0GK0CX15205426	Next Service:	66,000kms	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
	SW		SW SW		S W	Performance	~		
Key:	LSW [-0	SW SW		<u> </u>	Radiator / Hoses (visual)	~		
S = scratch D = dent R = rust PT = paint defect						Transmission			
						Operation	~		
						Noise	~		
C = crack					SC	Clutch			~
P = pin dent						CV joints	~		
* = decals SC 919 W						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC S SC W S W S						Performance	~		
Podylog	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body inspection comments						Tyres (lowest observed tread depth of tyres)			es)
No spare wheel, factory repair kit only.					Left front 5 mm				
						Right front		5	mm
						Left rear		5	mm
Conditions During Body Inspection: Wet						Right rear	6 mm		mm
Conditions During Body Inspection: Wet						Spare	No		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Clean & tidy.						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats drivers bolster foam worn.						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	· ·		
Panels	rear armre	sts worn, cargo s	shelf missing.			Dashboard warning lights	· ·		
						Wipers (front & rear)	• •		
Dashboa	rd Good					Window winder FL	• •		
						Window winder FR	• •		
General C	<u>Comments</u>					Window winder RL	~		
Low km hat	tch.					Window winder RR	• •		
						Rear view mirrors	• •		
						Radio (basic test only)	· ·		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	2		
Koad Con	ations During Test	Drive:	Dry			Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	•		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
		P							~
Inspected by: Daryll Timms Date: 09 Jul 2018									

I have read and understood this condition guide.

Name:

Signature: