

Report ID: 17,922,333 Version: 1 Created: 30 May 2018

Make:	Citroen	Model:	C5	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,003	Registration:	BJQ752	Reg Expiry:	01 Jul 2018	Engine			
l	13 Jul 2018	Odometer:	134,056 Kms	Good No:	17922333	Oil level	~		
VIN:	VF7DCXFXF76333082		due	Service Histor		Smoke & fumes	~		
	VI / DCAI AI / 05555002		duc		. 110	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance		~	
Key:	sc	-0	SW SW			Radiator / Hoses (visual)		V	
S = scratch						Transmission	~		
D = dent R = rust PT = paint defect C = crack									
						Operation Noise	~		
						Clutch		~	
C = crack P = pin dent									~
* = decals SC QQ						CV joints	~		
SC = stone chips						Wheel bearings			
W = significant scuffs SC S W						Brakes			
						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	1	1.0 mm	
						Right front	1.0		mm
						Left rear	1	.0	mm
Conditions During Body Inspection: Dry						Right rear	1.0		mm
Under Carriege & Under Permet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments					Suspension	1	1	-	
Front brake Coolant to	pads to change change					Suspension performance	~		
Bump stops on rear to be replaced						Steering performance	~		
Oil leak at rear right suspension Tyers all low						Shock absorbers	~		
						Air Conditioning / Heater		1	
						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
	Coord					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
	•					Window winder FR	~		
General Comments					Window winder RL	~			
Noise from trans Noise from left wheel bearing						Window winder RR	~		
Vibration thro car						Rear view mirrors	~		
Coolant low Engine light on						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
	d by Diese Matter	Data: 20 May 2010							
Inspected by: Dion Mair Date: 30 May 2018									
I have read and understood this condition guide. Name:									