

Report ID: 17,922,488 Version: 1 11 Jun 2018 Created:

Make:	Toyota	Model:	Avensis	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,007	Registration:		Reg Expiry:		Engine			
WoF Expiry:	18 May 2019	Odometer:	79,657 Kms	Good No:	17922488	Oil level	~		
VIN:	7AT0H63MX18007665	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Danta harra a st		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechani	ical inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
		_				Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	STE	A U			Xa.	Transmission			L
D = dent	6/6			1n-		Operation	~		
R = rust PT = paint defe				$\prod$	JHH	Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		<b> </b>
* = decals	616			The	ETTPS-	Wheel bearings	~		
SC = stone chip	/	20		1al		Brakes	•		
W = significant	scuffs	-				Performance	~		<u> </u>
		Note: som	le defects & blemishes	may not be disr	blayed in the diagram	Hand Brake	~		
Body Insp	ection Comments	Note: Joh		indy not be disp	nayed in the diagram	Tyres (lowest observed tread		oftyre	
						Left front			mm
						Right front	4.		-
						Left rear	4.		mm
							4.	-	mm
Conditions During Body Inspection: Dry						Right rear	4.		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	<u>incernspectio</u>	<u>in comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			<del></del>
Interior Comments						Operation	~		
Good						Electrical / Accessories			
Seats						Head lights	~		──
Carpets	Good					Tail lights	~		<b> </b>
	Good					Indicators	~		<b> </b>
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Ganaral	omments					Window winder FR	~		<u> </u>
						Window winder RL	~		<u> </u>
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		<u> </u>
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	3		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		<u> </u>
Enging Tir	ning Machanism	<b></b>	<b>7</b> 1 • .			Remote locking	~		<u> </u>
-	ning Mechanism:	Timing (		/ w		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected	by: Bobby Zhong					Date: 28 May 20	18		
	. 27. 2000y Zhong								

I have read and understood this condition guide.

Name: .....