

Report ID: 17,923,804 Version: 1 Created: 29 May 2018

Make:	Nissan	Model:	Leaf	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,014	Registration:	KFG392	Reg Expiry:	06 Jun 2018	Engine			
WoF Expiry:		Odometer:	38,725 Kms	Good No:	17923804	Oil level	~		
VIN:	7AT0DH8KX16101556	Next Service:	50,725 14115	Service Histor		Smoke & fumes			~
						Performance			~
	port is not a warranty		с I II			Noise			~
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
		_				Performance	•		~
Key:		-0				Radiator / Hoses (visual)			~
S = scratch						Transmission			
D = dent	- Alle			The	EID S	Operation	~		
R = rust				10	JHIH	Noise	V		~
PT = paint def C = crack	ect M			+		Clutch			-
P = pin dent	Ho								~
* = decals	- MIR			AL-		CV joints Wheel bearings	~		
SC = stone chi	ps US	VA		10	& <u> </u>		~		
W = significant scuffs						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake		<i>c</i> .	Ļ
						Tyres (lowest observed tread	d depth	of tyre	
						Left front	4	1	mm
						Right front	4	ł	mm
						Left rear	4	ł	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments					Spare	No			
	mage & Under Bor	inet inspectic	on comments			Suspension			
Clean						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments Good						Electrical / Accessories	5		
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet Central locking									
						Remote locking	~		
•	ming Mechanism:	Unknow	'n			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Stuart Melbourne Date: 29 May 2018									

I have read and understood this condition guide.

Name:

Signature: