

Basic Vehicle Condition Guide

Report ID: 17,924,366


Version:

Created: 29 May 2018

Make: Model: Hilux **Body Style:** Utility Toyota Year: 2,009 Registration: **EWY278** Reg Expiry: 10 Jul 2018 WoF Expiry: **Odometer:** 30 May 2019 **Good No:** 202,377 Kms 17924366 VIN: MR0FZ22G301024391 **Next Service: Service History:** 209,000kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Sills dented.

2 rear bumper plastics missing.

Stone chips on screen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

| | Interior Comments | 2 |
|--|-------------------|---------------------------------|
| | Seats | drivers seat ripped, dirty. |
| | Carpets | Average |
| | Panels | Average |
| | Dashboard | right vent broken, screw holes. |

General Comments

Inspected by:

Squeaky clutch peddle, works fine.

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: Kms: Yes 150,000

> 29 May 2018 Date:

| | Pass | Fail | N/A | | |
|----------------------------------------------|---------------------------------------|------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | <i>v</i> | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | • | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | \(\times \) | | | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 8 | 3 | mm | | |
| Right front | 8 | 3 | mm | | |
| Left rear | 7 | 7 | mm | | |
| Right rear | (| 5 | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | V | | | | |
| Dashboard warning lights | ~ | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 4 | ı | | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

I have read and understood this condition guide.

Name:

Signature: