

Report ID: 17,924,833 Version: 2 15 Jun 2018 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail N/A
Year:	2,013	Registration:	GTS645	Reg Expiry:	26 Jul 2018	Engine		
	14 Jun 2019	Odometer:	92,006 Kms	Good No:	17924833	Oil level	~	
VIN:	KL3CD265JCB119174	Next Service:		Service Histor		Smoke & fumes	~	
	RESCO2055CD115174		Duc.		. 110	Performance	~	
	port is not a warranty					Noise	~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition		
						Performance	v v	
Key:		-0	lsls			Radiator / Hoses (visual)	~	
S = scratch						Transmission		
D = dent	IS OF			The	BID		~	
R = rust				10	JHIN	Operation Noise	~	
PT = paint def C = crack	ect M			+		Clutch	~	
P = pin dent	LHC	KI						~
* = decals	sc pp					CV joints	~	
SC = stone chi	ps U	LA		10	\$P	Wheel bearings	~	
W = significant scuffs						Brakes		
		Nata				Performance	~	
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake		
						Tyres (lowest observed tread depth of tyres)		
						Left front	5	mm
						Right front	5	mm
					Left rear	2	mm	
Conditions During Body Inspection: Wet						Right rear	4 mm	
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes	
<u>Under Ca</u>	mage & Under Bor	net inspectic	on comments			Suspension	,	
						Suspension performance	~	
						Steering performance	~	
						Shock absorbers	~	
						Air Conditioning / Heater		
						Operation 🖌		
Interior Comments Good						Electrical / Accessories		
Seats	Good					Head lights	~	
Carpets	Good					Tail lights	~	
						Indicators	~	
Panels	Good					Dashboard warning lights	~	
Dashboa	rd Good					Wipers (front & rear)	~	
						Window winder FL	~	
						Window winder FR	~	
General C	<u>Comments</u>					Window winder RL	~	
						Window winder RR	~	
						Rear view mirrors	~	
						Radio (basic test only)	~	
						CD (basic test only)	~	
						Number of keys	2	
Road Conditions During Test Drive: Wet						Central locking	~	
	-					Remote locking	~	
	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~	
Inspected by: Jason Law Date: 15 Jun 2018								

I have read and understood this condition guide.

Name:

Signature: