

Report ID: 17,927,522 Version: 4 20 Jun 2019 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2014	Registration:	HWJ168	Reg Expiry:	12 Dec 2019	Engine			
WoF Expiry:	20 Jun 2020	Odometer:	200,859 Kms	Good No:	17927522	Oil level	~		
VIN:	KL3CD2669FB021565	Next Service:	213,000 kms	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged f	or an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	S D SC		sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC 615			715	HILW	Operation	~		
R = rust PT = paint def				$\left[\right] \left[\right]$		Noise	~		
C = crack				$+ \mathbf{\nabla}$	SC	Clutch			~
P = pin dent	110				세비	CV joints	~		-
* = decals	DSC 916			The	AIR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC D SC SC W						Performance	~		
D. L.L.		Note: son	ne defects & blemishe	s may not be disp	blayed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	-	of tvre	s)
Tailgate rubber torn. Chrome grille in poor condition						Left front 6 mm			
						Right front	5		mm
						Left rear		7	mm
Condition	as During Pody Inc	oction	Dmr			Right rear		7	 mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	•	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		I
						Operation	~		
Interior Comments						Electrical / Accessories			
Good Good						Head lights			
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
Faileis						Wipers (front & rear)	~		
Dashboa	Ird Good					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Dead Canditions Duving Test Driver 2						Central locking	2 V		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)	~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera	~		
	-1	•	- 1.6						
Inspected by: Stuart Melbourne Date: 20 Jun 2019									

I have read and understood this condition guide.

Name: