

Report ID: 17,928,518 Version: 3 Created: 22 Jun 2018

Make:	Mitsubishi	Model:	Pajero	Body Style:	Wagon		Pass	Fail	N/A
Year:	2,000	Registration:	AQW393	Reg Expiry:	15 Aug 2018	Engine			L
	2,000 13 Jun 2019	Odometer:	260,380 Kms	Good No:	17928518	Oil level	~		
VIN:	7A8CJ080702007464	Next Service:	242,655kms	Service Histor		Smoke & fumes	~		
	7860080702007404		242,033KITIS		• NO	Performance	~		
Note: This report is not a warranty						Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
Key:	S SC S	M S	SW SW		W	Performance	~		
S=scratch						Radiator / Hoses (visual)	~		
D = dent						Transmission			
R = rust	sscw 96				SHUK	Operation		~	
PT = paint def	ect N			$ \rangle$	R SC W	Noise	~		
C = crack P = pin dent	Ille					Clutch			~
* = decals	PSCW				THE	CV joints	~		
* = decals S R PT SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
SCW SW W SW SW SPW						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
						Tyres (lowest observed tread	d depth	of tyre	es)
					Left front 3.6			mm	
						Right front	3	.3	mm
						Left rear	3	3.8 m	
Conditions During Body Inspection: Wet						Right rear	3.0 mi		mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Good				Dashboard warning lights		>		
Deckle	rd Good					Wipers (front & rear)	~		
Dashboa	iu					Window winder FL	~		
	_					Window winder FR	~		
General Comments Transmission needs attention. GPS keeps saying load fail! Engine check light showing on dash display.						Window winder RL	~		
Transmissic	on needs attention. GPS	keeps saying loa	ad fail! Engine check lig	ght showing on d	ash display.	Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	t Drive:	Wet]	Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)		~	
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 20	7,991	Reversing camera	~		
	dha ti Y								
Inspected by: Jason Young Date: 06 Jun 2018									
I have read and understood this condition guide. Name:									