

Basic Vehicle Condition Guide

Report ID: 17,928,556


Version:

Created: 01 Jun 2018

Make: Model: Fiat Punto **Body Style:** Hatchback Year: 2,014 Registration: HUT877 Reg Expiry: 30 Nov 2018 WoF Expiry: **Odometer: Good No:** 17928556 12 Jun 2019 119,643 Kms VIN: ZFA1990000P025637 **Next Service: Service History:** 135,000kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

R/R door handle faulty or broken.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

<u>Interior Comments</u>			
Seats	Average		
Carpets	Average		
Panels	Average		
Dashboard	Good		

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: Kms: Yes 102,000

> 01 Jun 2018 Date:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	v v		
Performance	~		
Noise	~		
Cooling System	•		
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		3	mm
Right front		4	mm
Left rear	:	3	mm
Right rear		4	mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		
Operation	~		
Electrical / Accessories	1		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	v v		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1	1	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

I have read and understood this condition guide.

Name:

Signature: