

Basic Vehicle Condition Guide

Report ID: 17,928,732


Version: 3

Created: 25 Jun 2018

Make: Model: Mazda Bt-50 **Body Style:** Utility Year: 2,008 Registration: EGW924 Reg Expiry: 17 Apr 2018 WoF Expiry: **Odometer: Good No:** 21 Jun 2019 17928732 181,981 Kms VIN: **Next Service:** MM0UNY0E30067163 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

FR park light not working Wing mirrors not working

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Holes on A pillar trim RH side		
Dashboard	Holes drilled		

General Comments

Engine noisy

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise		~	
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission	•	•	
Operation	~		
Noise	~		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	5		mm
Right front	5		mm
Left rear	7		mm
Right rear	7		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	ı		-
Operation	~		
Electrical / Accessories	l		
Head lights	~		
Tail lights	~		
Indicators			
Dashboard warning lights	V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors		~	
Radio (basic test only)	~	-	
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking		~	
Sat. Nav. (basic test only)			·
	1	i .	

Reversing camera

1

Signature:

25 Jun 2018 Inspected by: **Bobby Zhong**

Name: