

Basic Vehicle Condition Guide

Report ID: 17,928,807

Pass

1

/

/

V

1

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Operation

Head lights Tail lights Indicators

Suspension performance Steering performance

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 05 Jun 2018

Fail

N/A

1

mm

mm

mm

 mm

5

5

5

1

/

/

1

1


1

Yes

Make: Model: 4007 **Body Style:** SUV Peugeot Year: Registration: GDT116 **Reg Expiry:** 2,011 07 Dec 2018 **WoF Expiry: Odometer: Good No:** 11 Nov 2018 87,420 Kms 17928807 VIN: VF3VV4HK8BU802615 **Next Service: Service History:** 105000 Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:** No

Xinghui Lin

I have read and understood this condition guide.

Kms:	Sat. Nav. (basic test only) Reversing camera	<i>V</i>		
Date: 05 Jun 2018				
Name:	Signature:			