

I have read and understood this condition guide.

Report ID: 17,929,857 Version: 2 Created: 10 Aug 2018

Signature:

Make:	Holden	Model:	Rodeo 4X4	Body Style:	Utility		Pass	Fail	N/A
Year:	2,006	Registration:	DMM464	Reg Expiry:	30 Nov 2018	Engine	I	L	
WoF Expiry:	02 Aug 2019	Odometer:	151,698 Kms	Good No:	17929857	Oil level	~		
VIN:	MPATFS26H4H556737	Next Service:	159000	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	anation is maada	for one and miles as	Danta hava nat	heen dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	D*SC	-0	* D * SC		S D *	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S R SC			1n-	EII SR	Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack				$+$ \vee		Clutch	~		
P = pin dent						CV joints	~		
* = decals	*sc 916			AL.		Wheel bearings	~		
SC = stone chips						Brakes			L
W = significant scuffs * W S D R * D R * SC S *						Performance	~		
		Noto: com				Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofturo	
Holes in bumper Fuel flap alignment						Tyres (lowest observed tread depth of tyres) Left front 9			
Aerial holes on roof						Right front	9 mm		
						Left rear		0	mm
							6 mm		
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	inage a onder bor	ince inspectie	<u>eominents</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		<u> </u>
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Hole in drivers seat, marks on rear seat						Electrical / Accessories			
Seats						Head lights		~	
Carpets	Hole in fro	nt passenger ma	t			Tail lights	~		
	Scratches	on rear door pan	olc			Indicators	~		
Panels	Sciatches		C15			Dashboard warning lights	~		
Dashboa	rd Holes in da	ashboard				Wipers (front & rear)	~		
	-					Window winder FL	~		
Concret	Comments					Window winder FR	~		$\left \right $
						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		$\left \right $
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking							~		
Enging Ti	ming Machanism		-			Remote locking		~	<u> </u>
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms: Reversing camera									~
Inspected by: John Lindsay Date: 10 Aug 2018									

Name: