

## **Basic Vehicle Condition Guide**

Report ID: 17,929,959


Version: 1

Created: 24 Jun 2018

Make: Model: Holden Commodore **Body Style:** Sedan Year: 2,014 Registration: Reg Expiry: HPS700 27 Aug 2018 WoF Expiry: **Odometer: Good No:** 17929959 28 Aug 2018 45,529 Kms VIN: **Next Service: Service History:** 6G1FJ5E3XEL987604 56000 Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Wet

**Conditions During Body Inspection:** 

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comment	<u>S</u>
Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Xinghui Lin

Evidence of Cam Belt Replacement: Not Applicable Kms:

Pass	Fail	N/A
>		
~		
/		
~		
~		
~		
/		
		•
~		
/		
		~
		~
~		
	•	
>		
<b>'</b>		
l depth	of tyre	es)
	5	mm
	5	mm
	,	
	.5	mm
3		
3	.5	mm
3	.5 .5	mm
3 3 V V V	.5 .5	mm
3 3 V V V	.5 .5	mm
3 3 V V	.5 .5	mm
3 3 V V V	.5 .5	mm
3 3 V V V V	.5 .5	mm
3 3 V V V V V	.5 .5	mm
3 3 V V V V V V V	.5 .5	mm
3 3 V V V V V V V	.5 .5	mm
3 3 V V V V V	.5 .5	mm
3 3 V V V V V V V	.5 .5	mm
		· ·

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Date:

2

24 Jun 2018

~