

Report ID: 17,930,776 Version: 1 13 Jun 2018 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2,013	Registration:	HEP362	Reg Expiry:	18 Jun 2018	Engine			
WoF Expiry:	19 Dec 2018	Odometer:	105,000 Kms	Good No:	17930776	Oil level	~		
VIN:	MNTVCGD40A060061	Next Service:	105,543kms	Service History	V: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	sc	-0	SC W P SC		SC W	Radiator / Hoses (visual)	· ·		
S = scratch						Transmission			
D = dent				The		Operation	~		
R = rust PT = paint defe				\prod		Noise	~		
C = crack				$+ \vee$	D	Clutch	· ·		
P = pin dent					세비	CV joints	•		~
* = decals	sc 916			AL.	ELLAR W	Wheel bearings	~		•
SC = stone chips						Brakes			
W = significant scuffs SC SC SC SC SC						Performance	~		
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~		
Body Insp	pection Comments			.,		Tyres (lowest observed tread	-	of tyre	
						Right front	4		 mm
						Left rear	3		mm
Canalitian	- Dunin n De du la s					Right rear			mm
Conditions During Body Inspection: Wet						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension	Yes		
OK.	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Danala	Average					Dashboard warning lights	v v		
Panels						Wipers (front & rear)	v v		
Dashboa	rd Average					Window winder FL	v v		
						Window winder FR	v v		
General C	Comments					Window winder RL	v v		
Good 2WD						Window winder RL	v v		
						Rear view mirrors	v v		
						Radio (basic test only)	v v		
						CD (basic test only)	~		
						Number of keys			
Road Conditions During Test Drive: Wet						Central locking	2		
Koad Con	attions During Tes	u Drive:	Wet			Remote locking	v v		
Engine Tir	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	•		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									~
Inspected by: Daryll Timms Date: 13 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: