

Report ID: 17,930,782 Version: 1 13 Jul 2018 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,008	Registration:	EQM902	Reg Expiry:	19 Nov 2018	Engine	1	1	1
WoF Expiry:	06 Dec 2018	Odometer:	138,343 Kms	Good No:	17930782	Oil level	~		T
VIN:	JSAEZC21S00423678	Next Service:	145000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission	-		
D = dent	s di			TIN		Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack				+		Clutch	~		
P = pin dent					ᅰЦ	CV joints	~		
* = decals	sc 916			- AL	ETTPS-	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs PT S						Performance	~		
		Note: son	he defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre	
						Tyres (lowest observed tread depth of tyres)			
						Right front	6		mm
						Left rear	4		
							4		mm
Conditions During Body Inspection: Dry						Right rear	4.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare No			
No oil leaks						Suspension			1
INO OII IEAKS						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation	~		
Good						Electrical / Accessories	1		T
Seats						Head lights	~		<u> </u>
Carpets	Good					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concert						Window winder FR	~		<u> </u>
General Comments Lights cut and polish						Window winder RL	~		
Lights cut a	na polisn					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
			-			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms:		Reversing camera			~
Increasted by Den							10		
Inspected by: Ron Date: 14 Jun 2018									
I have read	and understood th	is condition q	juide. Name: .			Signature:			