

Basic Vehicle Condition Guide

Report ID: 17,931,586

Pass

V

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Coolant condition Performance

Created: 07 Jun 2018

Fail


N/A

mm mm mm mm

Make: Model: **Body Style: Great Wall** X240 Wagon Year: 2,011 Registration: GBJ311 Reg Expiry: 08 Jul 2018 **WoF Expiry: Odometer: Good No:** 12 Feb 2019 17931586 69,814 Kms Service History: VIN: LGWFF3A57BB642637 **Next Service:** 79485kms Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



I have read and understood this condition guide.

Name:	 Signature:	

c	= scratch	\sim (0) \sim	Radiator / Hoses (visual)	~		
	= dent		Transmission			
	= rust SC W	1 dia Sow	Operation	~		Γ
	T = paint defect		Noise	~		T
	= crack		Clutch	~		T
P	= pin dent		CV joints	~		T
	= decals R SC	J M M Sc	Wheel bearings	~		T
	C = stone chips		Brakes	1		_
V۱	/ = significant scuffs	S SSCW D	Performance	V		Τ
	Body Inspection Co	Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~		T
	• •	dscreen in engine bay and along firewall	Tyres (lowest observed tread	d depth	of tyre	es)
		domly through engine bay	Left front	,	 6	m
	Wiper arms rusty LF mudflap broken off		Right front		7	m
	Li iliddilap brokeri oli		Left rear		4	m
	Conditions During	Body Inspection: Dry	Right rear		<u>.</u> 5	m
	Containons Daning	Dody inspection.	Spare		Yes	
	Under Carriage & U	nder Bonnet Inspection Comments	Suspension			
		arms rusty possible beach use	Suspension performance	~		Τ
	Front bumper / chassis	support very rusty	Steering performance	~		t
			Shock absorbers	~		t
			Air Conditioning / Heater	1		_
			Operation	~		Т
	Interior Comments		Electrical / Accessories			
	Seats	Good	Head lights	~		Т
		Good	Tail lights	~		t
	Carpets	Good	Indicators	~		t
	Panels	Good	Dashboard warning lights	~		t
	1 411013		Wipers (front & rear)	~		t
	Dashboard	good but has some glue and marks on passenger side	Window winder FL	~		t
			Window winder FR	~		t
	General Comments		Window winder RL	~		t
Drives ok			Window winder RR	~		t
	Coolant additive conce	Rear view mirrors	~		+	
			Radio (basic test only)	~		t
			CD (basic test only)	~		H
			Number of keys	2		_
	Road Conditions Du	uring Tost Drivo	Central locking	·		Т
_		iring Test Drive: Dry	Remote locking	~		+
	Engine Timing Mec	nanism: Cambelt	Sat. Nav. (basic test only)	<u> </u>		+
	Evidence of Cam Be	lt Replacement: No Kms:	Reversing camera	~		
	Inspected by: Roge	r King	Date: 07 Jun 201	18		
-						_