

Report ID: 17,932,024 Version: 1 Created: 03 Jun 2018

Make:	Honda	Model:	Integra	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2,005	Registration:	KJE229	Reg Expiry:	20 Jan 2018	Engine	1	L	L
WoF Expiry:	,	Odometer:	109,272 Kms	Good No:	17932024	Oil level	~		
VIN:	7AT08G0RX16302487	Next Service:	Overdue .	Service Histor		Smoke & fumes	~		
						Performance	•	~	
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismontiad as						Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
						Performance	· ·		
Key:		-0	S L		S	Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		<u> </u>
D = dent						Operation		~	
R = rust				10	JHIH	Noise		~	
PT = paint defect C = crack						Clutch		~	
P = pin dent						CV joints		~	
*= decals S P P						Wheel bearings		V	
SC = stone chips						Brakes	~		
W = significant scuffs S S S S S S S S S S S S S S S S S S									
							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
RR quarter glass missing						Tyres (lowest observed tread		,	,
Rear bumper misaligned 2nd key need attention						Left front			mm
Front wiper washer not working						Right front	0 mm		
RH wina mirror not retractina						Left rear	3 mm		
Conditions During Body Inspection: Dry						Right rear	4 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder carnage & onder bonnet inspection comments					Suspension				
						Suspension performance		~	
						Steering performance	~		
						Shock absorbers		~	
						Air Conditioning / Heater			
Interior Comments						Operation		~	
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Poor					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa	ru –					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL			~
FL park light not working , Audio not working AC not working						Window winder RR			~
Excessive noise from engine bay						Rear view mirrors	~		
Transmission noisy, clutch weak Front suspension very weak and noisy						Radio (basic test only)		~	
		,				CD (basic test only)		~	
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						_			
Inspected by: Mathew Varghese Date: 03 Jun 2018									
I have read and understood this condition guide. Name:									