

Report ID: 17,933,136 Version: 1 Created: 21 Jun 2018

Make:	Mazda	Model:	Premacy	Body Style:	SUV		Pass	Fail	N/A
Year:	2,006	Registration:	,	Reg Expiry:	-	Engine	I	L	L
WoF Expiry:	01 Jun 2019	Odometer:	98,120 Kms	Good No:	17933136	Oil level	~		
VIN:	7AT0C133X18139693	Next Service:	108000	Service Histor		Smoke & fumes	~		+
						Performance	~		
	port is not a warranty		C 1 11		I IS ALL	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-161-		Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission			<u> </u>
D = dent	- HE			The		Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack				+		Clutch			~
P = pin dent						CV joints	~		
* = decals	- 91E			- NL	III	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs	$- \emptyset$				Performance	~		
		Note: son	ne defects & blemishes	may not be dis	blayed in the diagram	Hand Brake	~		
Body Insp	pection Comments					Tyres (lowest observed tread	-	of tyre	<u> </u>
						Left front 4.0 mm			
						Right front	4		mm
						Left rear			mm
Conditions During Pody Inspection, West						Right rear			mm
Conditions During Body Inspection: Wet						Spare	1.0		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		L
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Cood					Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		<u> </u>
						Wipers (front & rear)	~		+
Dashboa	rd Good					Window winder FL	~		<u> </u>
						Window winder FR	~		
General Comments						Window winder RL	~		<u> </u>
						Window winder RR	~		+
						Rear view mirrors	~		+
						Radio (basic test only)	~		+
						CD (basic test only)	~		+
						Number of keys	2		L
Road Conditions During Test Drive: Wet						Central locking	2 V		
			Wet			Remote locking	~		<u> </u>
Engine Ti	ming Mechanism:	Timing	Chain			Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
							1		
Inspected by: Bobby Zhong Date: 05 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: