

Report ID: 17,933,297 Version: 1 Created: 05 Jun 2018

Make: S	Suzuki	Model:	Splash	Body Style:	Hatchback		Pass	Fail	N/A
	2,009	<b>Registration:</b>		Reg Expiry:		Engine	1		L
WoF Expiry: 0	)1 Jun 2019	Odometer:	56,184 Kms	Good No:	17933297	Oil level	~		
		Next Service:	66100	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	r		
	ort is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanica	al inspection prior to	purchase and th	his can be arranged fo	r an additional o	charge.	Coolant condition	~		
						Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715	HIV	Operation	~		
PT = paint defect				$\left( \left  \left( \right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HIR				7414	CV joints	~		
* = decals	MAK			The second		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
vv – significant s						Performance	~		
Body Inspe	action Comments	Note: som	e defects & blemishes	may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments						<b>Tyres</b> (lowest observed tread depth of tyres)			
						Left front			
						Right front		5	mm
						Left rear	4	1	mm
Conditions During Body Inspection: Wet						Right rear		5 mm	
vet						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension	I		
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboard	a					Window winder FL	~		
						Window winder FR	~		
General Co	omments					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of	f Cam Belt Replace	ement: N	lot Applicable	Kms:		Reversing camera			~
In							10		
Inspected b	by: Bobby Zhong					Date: 05 Jun 20	١ð		

I have read and understood this condition guide.

Name: .....