

Report ID: 17,933,617


Version:

Created: 08 Jun 2018

Make:	Toyota	Model:	Wish	Body Style:	SUV
Year:	2,006	Registration:		Reg Expiry:	
WoF Expiry:	23 May 2019	Odometer:	95,670 Kms	Good No:	17933617
VIN:	7AT0H64BX18294137	Next Service:	105,665kms	Service History	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

Interior Comments					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Nice 7 seater wagon.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Kms: Not Applicable

Daryll Timms Date: 08 Jun 2018 Inspected by:

Name:

	Pass	Fail	N/A
Engine		1	
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	V		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes	1		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front		4	mm
Right front		4	mm
Left rear		4	mm
Right rear		4	mm
Spare		Yes	
Suspension	ı		
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater	1		
Operation	~		
Electrical / Accessories	1		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V V V V V		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: