

Basic Vehicle Condition Guide

Report ID: 17,933,714


Version: 3

Created: 17 Oct 2018

Make: Model: Subaru Exiga **Body Style:** Wagon Year: 2008 Registration: Reg Expiry: WoF Expiry: **Odometer: Good No:** 22 May 2019 17933714 100,117 Kms VIN: 7AT0GF1RX18002305 **Next Service:** Service History: 110,100kms

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments			
Seats	Good		
Carpets	Good		
Panels	Good		
Dashboard	Good		

General Comments

Tidy 2WD, 7 seater wagon . CAMBELT HAS BEEN CHANGED RECENTLY

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Kms: Yes 100,138

07 Jun 2018 Inspected by: **Daryll Timms** Date:

Name:

	D	F-:1	NI/A	
Engino	Pass	Fail	N/A	
Engine Oil level				
Smoke & fumes				
	\(\times \)			
Performance Noise	<i>V</i>			
	<i>V</i>			
Cooling System Coolant condition				
Performance	-			
	<i>v</i>			
Radiator / Hoses (visual)	•			
Transmission				
Operation	•			
Noise	-			
Clutch			-	
CV joints	-			
Wheel bearings	'			
Brakes	ı	I		
Performance	~			
Hand Brake	~	_		
Tyres (lowest observed tread depth of tyres)				
Left front	1	.0	mm	
Right front	0.0		mm	
Left rear	4.0		mm	
Right rear	4.0		mm	
Spare		Yes		
Suspension		1		
Suspension performance	~			
Steering performance	V			
Shock absorbers	~			
Air Conditioning / Heater	1	ı	1	
Operation 🗸				
Electrical / Accessories	ı	I	1	
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	\(\times \)			
Wipers (front & rear)				
Window winder FL	~			
Window winder FR	~			
Window winder RL	~			
Window winder RR	~			
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	2	1		
Central locking	~			
Remote locking	~			
Sat. Nav. (basic test only)			~	
Reversing camera			'	

Signature: