

Basic Vehicle Condition Guide

Report ID: 17,933,896


Version:

Created: 26 Jun 2018

Make: Model: Subaru Outback **Body Style:** SUV Year: 2,014 Registration: **HPH478** Reg Expiry: 30 Jul 2018 WoF Expiry: **Odometer:** 31 Jul 2018 **Good No:** 17933896 101,877 Kms VIN: JF2BRMKC5EG064370 **Next Service: Service History:** 112500

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|------|--|--|
| Seats | Good | | |
| Carpets | Good | | |
| Panels | Good | | |
| Dashboard | Good | | |

General Comments

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Eddie Marsters Date: 26 Jun 2018

| | Pass | Fail | N/A | |
|------------------------------|-----------------|---------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | v v | | | |
| Performance | ~ | | | |
| Noise | ~ | | | |
| Cooling System | | | | |
| Coolant condition | ~ | | | |
| Performance | \(\triangle \) | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | | | ~ | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | |
| Left front | 6 | .5 | mm | |
| Right front | 6.5 | | mm | |
| Left rear | 5.5 | | mm | |
| Right rear | 5.5 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | <i>V</i> | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | • | | | |
| Electrical / Accessories | | | I | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | ~ | | | |
| Dashboard warning lights | <i>'</i> | | | |
| Wipers (front & rear) | V V V V V V V | | | |
| Window winder FL | • | | | |
| Window winder FR | • | | | |
| Window winder RL | • | | | |
| Window winder RR | • | | | |
| Rear view mirrors | | | | |
| Radio (basic test only) | / | | | |
| CD (basic test only) | • | | | |
| Number of keys | 2 | | | |
| Central locking | <i>V</i> | | | |
| Remote locking | | | | |
| Sat. Nav. (basic test only) | | | ., | |
| Reversing camera | | | | |

I have read and understood this condition guide.

Name:

Signature: