

Report ID: 17,933,981 Version: 1 Created: 27 Jun 2018

Make:	Subaru	Model:	Legacy	Body Style:	Sedan		Pass	Fail	N/A
Year:	2,009	Registration:	FBG76	Reg Expiry:	11 Jun 2018	Engine			•
WoF Expiry:	08 Jun 2019	Odometer:	232,392 Kms	Good No:	17933981	Oil level	~		
VIN:	JF1BM9K92AG002461	Next Service:	242300	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged f	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	L SSC			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust SSC A S SC						Operation	~		
PT = paint defect						Noise	~		
C = crack					sc	Clutch			~
P = pin dent	In the				74116	CV joints	V		
* = decals SDSC 999						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = significant scutts SSC S SD SD S SD						Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	V		
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres)			
					Left front 2 m			mm	
						Right front		3	mm
						Left rear	6	5	mm
Conditions During Body Inspection: Dry						Right rear	nt rear 6 r		
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater		1	
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Donovan Matara Date: 27 Jun 2018									

I have read and understood this condition guide.

Name: