

Report ID: 17,934,609 Version: 1 Created: 08 Jun 2018

Make:	Honda	Model:	FIT	Body Style:	Hatchback] []	Pass	Fail	N/A
Year:	2,011	Registration:		Reg Expiry:		Engine			
WoF Expiry:	2,011 24 May 2019	Odometer:	87,804 Kms		17934609	Oil level	~		
VIN:	7AT08G2YX18109626	Next Service:	97,000kms	Service History		Smoke & fumes	~		
	74100021410105020		<i>57,</i> 000kms	,	. 110	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends									
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	STO	A CO		100	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	Transmission	v		
D = dent	GIE				EIU /	Operation	~		
R = rust					HIH	Noise	~		
PT = paint def C = crack	ect		-	+		Clutch			V
P = pin dent	Ho				<u>лш —</u>	CV joints	~		
* = decals	- MIK				EIN PAL	Wheel bearings			
SC = stone chi	ps US	VA		200	&	Brakes	~		
W = significant scuffs						Performance			1
		Noto: con	L dofocts & blomish		aved in the diagram		~		
l	pection Comments		le délècts à blemism	es may not be dispi	ayed in the diagram	Hand Brake			
No spare wheel, factory repair kit only .						Tyres (lowest observed tread			
						Left front	3		mm
						Right front	4		mm
[Left rear	3		mm
Conditions During Body Inspection: Dry							Right rear 3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare No			
	inage & onder bor	met inspectio	on comments			Suspension		-	
Tidy .						Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior C	ammanta					Operation	~		
Interior Comments Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Good					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	Good					Wipers (front & rear)	~		
						Window winder FL	2		
	-					Window winder FR	~		
General Comments					Window winder RL	<			
Good looki	ng little hybrid hatch .					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	3		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
						-			
Inspected by: Daryll Timms Date: 08 Jun 2018									

I have read and understood this condition guide.

Name:

Signature: