

Report ID: 17,934,645

Version:

Engine Oil level Smoke & fumes

Noise

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Suspension performance Steering performance

Shock absorbers Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear) Window winder FL Window winder FR

Window winder RL

Window winder RR Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Operation

Head lights Tail lights Indicators

Spare

Coolant condition Performance

Radiator / Hoses (visual)

Created: 25 Jun 2018

Fail

N/A

~

mm

mm

mm

 mm

2

2

1

/

1

~

1

2

Yes

Pass

~

/

1


1

Tyres (lowest observed tread depth of tyres)

Make:	Audi	Model:	A3	Body Style:	Hatchback
Year:	2,007	Registration:		Reg Expiry:	
WoF Expiry:	22 May 2019	Odometer:	60,042 Kms	Good No:	17934645
VIN:	WAUZZZ8P77A08693	Next Service:	70.018kms	Service History	y: No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

Interior Comments					
Seats	Good				
Carpets	Good				
Panels	Good				
Dashboard	Good				

General Comments

Inspected by:

OK.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Daryll Timms

I have read and understood this condition guide.

	Remote locking	~							
	Sat. Nav. (basic test only)			~					
Kms:	Reversing camera			'					
Date: 25 Jun 2018 Name: Signature:									